

## Technical Bulletin

No. TB-0003A, Release Date 4/20/2020



### REGULATOR REPAIR KITS

We are consolidating our repair kits to 2 part numbers instead of having multiple part numbers. Also we will be using SP designation to readily identify them. This change will take affect appx 4/30/2020.

For our 2" diaphragm regulators, kit 7740-19-SP will replace kits 7740-15 and 7740-15N. For our smaller 1.6" diaphragm regulators, kit 3740-19-SP will replace kit 3740-17.

Current Part No.		New Part No.	
7740-15	Kit, repair, 2",flat seal	7740-19-SP	Kit, repair, 2", seals
7740-15N	Kit, repair, 2",o-ring seal		
3740-17	Kit, repair, 1.6",CO2 seal	3740-19-SP	Kit, repair, 1.6", o-ring

Below are side by comparison pics of these kits.



Old 2" repair kits



New 2" repair kit



Old 1.6" repair kit



New 1.6" repair kit